



Date: 9.MAY.2024 22:10:10




Date: 9.MAY.2024 22:10:20

Band26_1.4MHz_QPSK_26740_1RB#0_3000~1000_3000~10000

Band26_1.4MHz_16QAM_26740_1RB#0_0.009~0.15_0.009~0.15




Date: 9.MAY.2024 22:10:28




Date: 9.MAY.2024 22:10:37

Band26_1.4MHz_16QAM_26740_1RB#0_0.15~30_0_0.15~30


Band26_1.4MHz_16QAM_26740_1RB#0_30~100_0_30~100




Date: 9.MAY.2024 22:10:46




Date: 9.MAY.2024 22:10:55






Date: 9.MAY.2024 22:11:42




Date: 9.MAY.2024 22:11:51

Band26_1.4MHz_QPSK_26783_1RB#0_3000~10000

Band26_1.4MHz_16QAM_26783_1RB#0_0.009~0.15




Date: 9.MAY.2024 22:12:00




Date: 9.MAY.2024 22:12:09

Band26_1.4MHz_16QAM_26783_1RB#0_0.15~3


Band26_1.4MHz_16QAM_26783_1RB#0_30~100




Date: 9.MAY.2024 22:12:17




Date: 9.MAY.2024 22:12:26






Date: 9.MAY.2024 22:43:28




Date: 9.MAY.2024 22:43:37

Band26_3MHz_QPSK_26705_1RB#0_3000~10000

Band26_3MHz_16QAM_26705_1RB#0_0.009~0.1
5_0.009~0.15




Date: 9.MAY.2024 22:43:46




Date: 9.MAY.2024 22:43:55

Band26_3MHz_16QAM_26705_1RB#0_0.15~30
0.15~30

Band26_3MHz_16QAM_26705_1RB#0_30~1000
30~1000



Date: 9.MAY.2024 22:44:03



Date: 9.MAY.2024 22:44:12