



Date: 11.MAY.2024 10:23:12




Date: 11.MAY.2024 10:23:21

Band26_3MHz_QPSK_27025_1RB#0_3000~10000

Band26_3MHz_16QAM_27025_1RB#0_0.009~0.15




Date: 11.MAY.2024 10:23:30




Date: 11.MAY.2024 10:23:38

Band26_3MHz_16QAM_27025_1RB#0_0.15~30


Band26_3MHz_16QAM_27025_1RB#0_30~1000




Date: 11.MAY.2024 10:23:47




Date: 11.MAY.2024 10:23:55






Date: 11.MAY.2024 10:54:34




Date: 11.MAY.2024 10:54:43

Band26_5MHz_QPSK_26815_1RB#0_3000~10000

Band26_5MHz_16QAM_26815_1RB#0_0.009~0.15_0.009~0.15




Date: 11.MAY.2024 10:54:52




Date: 11.MAY.2024 10:55:00

Band26_5MHz_16QAM_26815_1RB#0_0.15~30_0.15~30


Band26_5MHz_16QAM_26815_1RB#0_30~1000_30~1000





Date: 11.MAY.2024 10:55:09





Date: 11.MAY.2024 10:55:18





Band26_5MHz_QPSK_26915_1RB#0_3000~10000

Band26_5MHz_16QAM_26915_1RB#0_0.009~0.15



Band26_5MHz_16QAM_26915_1RB#0_0.15~30

Band26_5MHz_16QAM_26915_1RB#0_30~1000

