





Band26_10MHz_QPSK_26915_1RB#0_3000~10000


Band26_10MHz_16QAM_26915_1RB#0_0.009~0.15




Band26_10MHz_16QAM_26915_1RB#0_0.15~3


Band26_10MHz_16QAM_26915_1RB#0_30~1000








Date: 11.MAY.2024 11:31:12




Date: 11.MAY.2024 11:31:22

Band26_10MHz_QPSK_26990_1RB#0_3000~10000_3000~10000

Band26_10MHz_16QAM_26990_1RB#0_0.009~0.15_0.009~0.15




Date: 11.MAY.2024 11:31:30




Date: 11.MAY.2024 11:31:39

Band26_10MHz_QPSK_26990_1RB#0_0.15~30_0.15~30


Band26_10MHz_16QAM_26990_1RB#0_30~1000_30~1000





Date: 11.MAY.2024 11:31:47





Date: 11.MAY.2024 11:31:55





Band26_15MHz_QPSK_26865_1RB#0_3000~10000

Band26_15MHz_16QAM_26865_1RB#0_0.009~0.15



Band26_15MHz_16QAM_26865_1RB#0_0.15~3

Band26_15MHz_16QAM_26865_1RB#0_30~1000

