



Date: 10.MAY.2024 01:44:29




Date: 10.MAY.2024 01:44:38

Band66\_10MHz\_QPSK\_132022\_1RB#0\_30~100  
0\_30~1000

Band66\_10MHz\_QPSK\_132022\_1RB#0\_1000~3000  
00\_1000~3000




Date: 10.MAY.2024 01:44:47




Date: 10.MAY.2024 01:44:57

Band66\_10MHz\_QPSK\_132022\_1RB#0\_3000~20000  
0000\_3000~20000


Band66\_10MHz\_16QAM\_132022\_1RB#0\_0.009~0.15  
0.15\_0.009~0.15




Date: 10.MAY.2024 01:45:05




Date: 10.MAY.2024 01:45:14






Date: 10.MAY.2024 01:46:01




Date: 10.MAY.2024 01:46:10

Band66\_10MHz\_QPSK\_132322\_1RB#0\_30~100  
0\_30~1000

Band66\_10MHz\_QPSK\_132322\_1RB#0\_1000~3000  
00\_1000~3000




Date: 10.MAY.2024 01:46:19




Date: 10.MAY.2024 01:46:29

Band66\_10MHz\_QPSK\_132322\_1RB#0\_3000~20000  
0000\_3000~20000

Band66\_10MHz\_16QAM\_132322\_1RB#0\_0.009~0.15  
0.15\_0.009~0.15



Date: 10.MAY.2024 01:46:38



Date: 10.MAY.2024 01:46:46

