



Date: 10.MAY.2024 01:47:33




Date: 10.MAY.2024 01:47:42

Band66_10MHz_QPSK_132622_1RB#0_30~100
0_30~1000

Band66_10MHz_QPSK_132622_1RB#0_1000~3000
00_1000~3000




Date: 10.MAY.2024 01:47:51




Date: 10.MAY.2024 01:48:00

Band66_10MHz_QPSK_132622_1RB#0_3000~20000
0000_3000~20000


Band66_10MHz_16QAM_132622_1RB#0_0.009~0.15
0.15_0.009~0.15




Date: 10.MAY.2024 01:48:09




Date: 10.MAY.2024 01:48:18






Date: 10.MAY.2024 02:17:41

Band66_15MHz_QPSK_132047_1RB#0_30~100
0_30~1000




Date: 10.MAY.2024 02:17:50

Band66_15MHz_QPSK_132047_1RB#0_1000~30
00_1000~3000




Date: 10.MAY.2024 02:17:59

Band66_15MHz_QPSK_132047_1RB#0_3000~2
0000_3000~20000




Date: 10.MAY.2024 02:18:08


Band66_15MHz_16QAM_132047_1RB#0_0.009~
0.15_0.009~0.15




Date: 10.MAY.2024 02:18:17




Date: 10.MAY.2024 02:18:26






Date: 10.MAY.2024 02:19:13

Band66_15MHz_QPSK_132322_1RB#0_30~100
0_30~1000




Date: 10.MAY.2024 02:19:22

Band66_15MHz_QPSK_132322_1RB#0_1000~30
00_1000~3000




Date: 10.MAY.2024 02:19:31

Band66_15MHz_QPSK_132322_1RB#0_3000~2
0000_3000~20000




Date: 10.MAY.2024 02:19:41

Band66_15MHz_16QAM_132322_1RB#0_0.009~
0.15_0.009~0.15



Date: 10.MAY.2024 02:19:50



Date: 10.MAY.2024 02:19:59