



Date: 10.MAY.2024 09:48:32




Date: 10.MAY.2024 09:48:42

Band71\_5MHz\_16QAM\_133147\_1RB#0\_0.15~3  
0\_0.15~30

Band71\_5MHz\_16QAM\_133147\_1RB#0\_30~1000  
\_30~1000




Date: 10.MAY.2024 09:48:51




Date: 10.MAY.2024 09:49:01

Band71\_5MHz\_16QAM\_133147\_1RB#0\_1000~3000  
000\_1000~3000


Band71\_5MHz\_16QAM\_133147\_1RB#0\_3000~10000  
000\_3000~10000





Date: 10.MAY.2024 09:55:08





Date: 10.MAY.2024 09:55:17







Band71\_10MHz\_QPSK\_133297\_1RB#0\_0.009~0.15\_0.009~0.15


Band71\_10MHz\_QPSK\_133297\_1RB#0\_0.15~30\_0.15~30





Band71\_10MHz\_QPSK\_133297\_1RB#0\_30~100\_0\_30~1000

Band71\_10MHz\_QPSK\_133297\_1RB#0\_1000~3000\_00\_1000~3000









Band71\_10MHz\_QPSK\_133422\_1RB#0\_0.009~0.15\_0.009~0.15

Band71\_10MHz\_QPSK\_133422\_1RB#0\_0.15~30\_0.15~30



Band71\_10MHz\_QPSK\_133422\_1RB#0\_30~100\_0\_30~1000

Band71\_10MHz\_QPSK\_133422\_1RB#0\_1000~3000\_00\_1000~3000

