




NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID6\_NS  
\_01\_3000\_6000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID6\_NS  
\_01\_6000\_26000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID6\_NS  
\_01\_26000\_40000\_#1




NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID4\_NS  
\_01\_0.009\_0.15\_#1









NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID5\_NS  
\_01\_0.009\_0.15\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID5\_NS  
\_01\_0.15\_30\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID5\_NS  
\_01\_30\_1000\_#1




NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID5\_NS  
\_01\_1000\_3000\_#1









NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID18\_N  
S\_01\_1000\_3000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID18\_N  
S\_01\_3000\_6000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID18\_N  
S\_01\_6000\_26000\_#1




NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID18\_N  
S\_01\_26000\_40000\_#1









NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID16\_N  
S\_01\_26000\_40000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID17\_N  
S\_01\_0.009\_0.15\_#1




NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID17\_N  
S\_01\_0.15\_30\_#1




NTNV\_N77-3700-3980\_PC2\_30\_10\_H\_TID17\_N  
S\_01\_30\_1000\_#1












NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID6\_NS\_01\_30\_1000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID6\_NS\_01\_1000\_3000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID6\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID6\_NS\_01\_6000\_26000\_#1









NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID4\_NS\_01\_6000\_26000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID4\_NS\_01\_26000\_40000\_#1





NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID5\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID5\_NS\_01\_0.15\_30\_#1









NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID18\_NS  
\_01\_0.15\_30\_#1



NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID18\_NS  
\_01\_30\_1000\_#1



NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID18\_NS  
\_01\_1000\_3000\_#1



NTNV\_N77-3700-3980\_PC2\_30\_15\_L\_TID18\_NS  
\_01\_3000\_6000\_#1

