


# INTERTEK TESTING SERVICES

Report No.: HK10070783-1



Bandedge Plot – Pursuant to FCC Part 15 Section 15. 227 Requirement