



American Certification Body Inc.  
6731 Whittier Ave, Suite C110  
McLean, VA22101

Date: 10.02.2015

FCC ID: YMY030189

IC: 9157A-030189

Model Number: 030189/030190

**Subject: Compliance Statements in Host Manuals**

Dear Examiners,

Our client's product with the above listed product identification(s) is a low frequency transmitter. The product will be installed in cars before they will be placed into the market.

Hereby our client assures that the following caution statement as per CFR 47, §15.21 is included in the owner's manual of the cars:

The title **"CAUTION TO USERS"** or **"FCC WARNING"**: **"NOTE"** or relevant title and **"Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."**

In addition, our client also assures that the following statement will be included in the manual as per CFR 47, §15.19(a)(3) and RSS-GEN 8.4

**This device complies with Part 15 of the FCC Rules and Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation**

**Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes : (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.**

Yours sincerely,

A handwritten signature in blue ink, appearing to be 'TR'.

Thomas Ring  
Manager Certification

CSA Group Bayern GmbH  
Ohmstr. 1-4, 94342 Strasskirchen, Germany