

Phonetone Technology (Shenzhen) Co., Ltd.

Apr 28, 2024

Subject: Tuning and Adjustment of Signal booster, FCC ID: YYOV50IN-US59

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Guangwei Zhang

Guangwei Zhang
May 6, 2024