



47173 Benicia Street
Fremont, CA 94538
Tel: 510-771-1000
Fax: 510-661-0888

June 4, 2019

FCC OET

Dear FCC,

We (UL TCB) mistakenly issued the grant for FCCID: YZP-TWFDS001T during the upload process and prior to completing the Pre-Approval Guidance (PAG) process required for this DFS Master Device. We respectfully request dismissal of this application pending FCC review, pre-grant testing (of necessary) and approval of the PAG.

No devices labeled with this FCC ID have been sold in the US or in any other country.

Regards,

Mark Briggs
Director, UL Verification Services Wireless Certification Program
UL Verification Services