



802.11ac80_5290MHz_Chain 0 75.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 15:46:27

802.11ac80_5290MHz_Chain 1 75.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:20:03

802.11ac80_5290MHz_Chain 2 75.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:22:07

802.11ax160_5250MHz_RU_Full_Chain 0 156MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:22:39

802.11ax160_5250MHz_RU_Full_Chain 1
156MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:23:43

802.11ax160_5250MHz_RU_Full_Chain 2
155.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:26:41

802.11ax20_5260MHz_RU_Full_Chain 0
19.050MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 18.DEC.2024 15:57:42

802.11ax20_5280MHz_RU_Full_Chain 0 19MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 18.DEC.2024 15:58:59

802.11ax20_5320MHz_RU_Full_Chain 0
19.100MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 18.DEC.2024 16:00:17

802.11ax20_5260MHz_RU_Full_Chain 1 19MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 18.DEC.2024 18:30:45

802.11ax20_5280MHz_RU_Full_Chain 1 19MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 18.DEC.2024 18:32:03

802.11ax20_5320MHz_RU_Full_Chain 1
19.150MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 18.DEC.2024 18:33:17


802.11ax20_5260MHz_RU_Full_Chain 2 19MHz




802.11ax20_5280MHz_RU_Full_Chain 2 19MHz




802.11ax20_5320MHz_RU_Full_Chain 2
19.100MHz




802.11ax40_5270MHz_RU_Full_Chain 0
37.400MHz




802.11ax40_5310MHz_RU_Full_Chain 0
37.800MHz




802.11ax40_5270MHz_RU_Full_Chain 1
37.600MHz




802.11ax40_5310MHz_RU_Full_Chain 1
37.800MHz


ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:39:59

802.11ax40_5270MHz_RU_Full_Chain 2
37.600MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:43:38


802.11ax40_5310MHz_RU_Full_Chain 2
37.700MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:44:42


802.11ax80_5290MHz_RU_Full_Chain 0
77.200MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:11:46

802.11ax80_5290MHz_RU_Full_Chain 1 77MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:43:11

802.11ax80_5290MHz_RU_Full_Chain 2
77.200MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:48:20


5470-5725MHz

802.11a_5500MHz_Chain 0 16.850MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:32:57

802.11a_5580MHz_Chain 0 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:34:01

802.11a_5700MHz_Chain 0 16.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:35:17

802.11a_5720MHz_Chain 0 16.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:36:17

802.11a_5500MHz_Chain 1 16.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:46:44

802.11a_5580MHz_Chain 1 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:47:42

802.11a_5700MHz_Chain 1 16.750MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:48:49

802.11a_5720MHz_Chain 1 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:50:22

802.11a_5500MHz_Chain 2 16.750MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:51:11

802.11a_5580MHz_Chain 2 16.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:52:12

802.11a_5700MHz_Chain 2 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:53:29

802.11a_5720MHz_Chain 2 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 20:54:31

802.11ac160_5570MHz_Chain 0 154MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:19:13

802.11ac160_5570MHz_Chain 1 154MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:22:22

802.11ac160_5570MHz_Chain 2 153.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:30:44

802.11ac20_5500MHz_Chain 0 17.950MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:50:12

802.11ac20_5580MHz_Chain 0 17.750MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:51:35

802.11ac20_5700MHz_Chain 0 17.950MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:53:43

802.11ac20_5720MHz_Chain 0 17.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 16:55:33

802.11ac20_5500MHz_Chain 1 17.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 18:59:56

802.11ac20_5580MHz_Chain 1 17.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:00:54

802.11ac20_5700MHz_Chain 1 17.850MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:02:09

802.11ac20_5720MHz_Chain 1 17.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:03:09

802.11ac20_5500MHz_Chain 2 17.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:05:20

802.11ac20_5580MHz_Chain 2 17.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:07:05

802.11ac20_5700MHz_Chain 2 17.850MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:08:21

802.11ac20_5720MHz_Chain 2 17.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:07:21

802.11ac40_5510MHz_Chain 0 36.500MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:06:42

802.11ac40_5550MHz_Chain 0 36.300MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:07:10

802.11ac40_5670MHz_Chain 0 36.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:07:36

802.11ac40_5710MHz_Chain 0 36.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:08:06

802.11ac40_5510MHz_Chain 1 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:12:30

802.11ac40_5550MHz_Chain 1 36.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:13:00

802.11ac40_5670MHz_Chain 1 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:13:32

802.11ac40_5710MHz_Chain 1 36.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:14:02

802.11ac40_5510MHz_Chain 2 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:19:26

802.11ac40_5550MHz_Chain 2 36.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:19:56

802.11ac40_5670MHz_Chain 2 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:20:32

802.11ac40_5710MHz_Chain 2 36.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:21:07

802.11ac80_5530MHz_Chain 0 75.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:13:42

802.11ac80_5610MHz_Chain 0 75.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:14:20

802.11ac80_5690MHz_Chain 0 75MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:14:54

802.11ac80_5530MHz_Chain 1 75.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:18:07

802.11ac80_5610MHz_Chain 1 75.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:18:44

802.11ac80_5690MHz_Chain 1 75MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:19:21

802.11ac80_5530MHz_Chain 2 75.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:26:31

802.11ac80_5610MHz_Chain 2 75.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:27:10

802.11ac80_5690MHz_Chain 2 75.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:27:51

802.11ax160_5570MHz_RU_Full_Chain 0
155.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:44:49

802.11ax160_5570MHz_RU_Full_Chain 1
155.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 19:50:24

802.11ax160_5570MHz_RU_Full_Chain 2
155.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 21:31:31

802.11ax20_5500MHz_RU_Full_Chain 0
19.150MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:22:03

802.11ax20_5580MHz_RU_Full_Chain 0 19MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:23:01

802.11ax20_5700MHz_RU_Full_Chain 0
19.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 18.DEC.2024 17:24:07

802.11ax20_5720MHz_RU_Full_Chain 0
19MHz


ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 17:25:02

802.11ax20_5500MHz_RU_Full_Chain 1
19.100MHz


ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 19:25:16

802.11ax20_5580MHz_RU_Full_Chain 1
19MHz


ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 19:26:16

802.11ax20_5700MHz_RU_Full_Chain 1
19.150MHz


ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 19:27:29

802.11ax20_5720MHz_RU_Full_Chain 1
19MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai


Date: 18.DEC.2024 19:28:31

802.11ax20_5500MHz_RU_Full_Chain 2
19.100MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai


Date: 18.DEC.2024 21:33:59

802.11ax20_5580MHz_RU_Full_Chain 2
18.950MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai
Date: 18.DEC.2024 21:34:59

802.11ax20_5700MHz_RU_Full_Chain 2
19.050MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai
Date: 18.DEC.2024 21:36:12

802.11ax20_5720MHz_RU_Full_Chain 2
18.950MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai
Date: 18.DEC.2024 21:37:10

802.11ax40_5510MHz_RU_Full_Chain 0
37.700MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai
Date: 18.DEC.2024 17:34:51

802.11ax40_5550MHz_RU_Full_Chain 0
37.600MHz



ProjectNo.:2401Y27848E-RF Testert:Allen Bai
Date: 18.DEC.2024 17:35:21

802.11ax40_5670MHz_RU_Full_Chain 0
37.800MHz



ProjectNo.:2401Y27848E-RF Testert:Allen Bai
Date: 18.DEC.2024 17:35:49