

CIIPC Letter

TUV Rheinland of North America, Inc.
1279 Quarry Lane Suite A
Pleasanton, CA 94566

Date: October 10, 2019





REF: FCC ID, pursuant to section 2.1043, for FCC ID: Z5YNS-MBTHS
IC, pursuant to section RSP-100, for IC: 10828A-MBTHS

Dear Sir or Madam,

Pursuant to section 2.1043, **Compupal Group Corporation** Hereby submit a request for CIIPC to our Bluetooth Headset, model no.: NS-MBTHS, FCC ID: Z5YNS-MBTHS, Grant date: 2019-07-16.

Pursuant to section RSP-100, **Compupal Group Corporation** Hereby submit a request for CIIPC to our Bluetooth Headset, model no.: NS-MBTHS-C, IC: 10828A-MBTHS, Grant date: 2019-07-16.

Description of the change:

Original PCB Layout	New PCB layout	Purpose
		Update the antenna to improve wireless connection stability
		Update the MIC PCB Layout to improve call quality

Conducted output power and Radiated Spurious Emissions were retested with report 50297930 001.

The following documents from the original application remain unchanged, applicable and representative after CIIPC:

- Block Diagram
- Schematic Diagram
- Operation Description

Due to the CIIPC the following exhibit are changed:

- ID Label & Label location
- External Photos (file rename)
- Internal Photos (file rename)

Compliance / Responsibility statements:

- The product remains compliant with all the applicable rules and requirements once performed this CIIPC.

Sincerely,

For and on behalf of: Compupal Group Corporation

Peter Pan

Mr Peter Pan
Product Specialist