



**Plot on Configuration VHT40 / 5710 MHz / Peak / Port 3 / 1GHz~3GHz**




Date: 3.APR.2018 21:17:35

**Plot on Configuration VHT40 / 5710 MHz / Peak / Port 4 / 1GHz~3GHz**




Date: 3.APR.2018 21:33:29

**Plot on Configuration VHT80 / 5530 MHz / Average / Port 1 / 1GHz~3GHz**




Date: 3.APR.2018 21:42:33

**Plot on Configuration VHT80 / 5530 MHz / Average / Port 2 / 1GHz~3GHz**




Date: 3.APR.2018 22:02:43

**Plot on Configuration VHT80 / 5530 MHz / Average / Port 3 / 1GHz~3GHz**



Date: 3.APR.2018 22:05:57


**Plot on Configuration VHT80 / 5530 MHz / Average / Port 4 / 1GHz~3GHz**




Date: 3.APR.2018 22:20:11



Plot on Configuration VHT80 / 5530 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration VHT80 / 5530 MHz / Peak / Port 2 / 1GHz~3GHz






Plot on Configuration VHT80 / 5530 MHz / Peak / Port 3 / 1GHz~3GHz




Date: 3 APR 2018 22:06:52

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 4 / 1GHz~3GHz




Date: 3 APR 2018 22:21:00

**Plot on Configuration VHT80 / 5610 MHz / Average / Port 1 / 1GHz~3GHz**




Date: 3.APR.2018 22:24:21

**Plot on Configuration VHT80 / 5610 MHz / Average / Port 2 / 1GHz~3GHz**




Date: 3.APR.2018 22:42:58

**Plot on Configuration VHT80 / 5610 MHz / Average / Port 3 / 1GHz~3GHz**



Date: 3.APR.2018 22:45:27


**Plot on Configuration VHT80 / 5610 MHz / Average / Port 4 / 1GHz~3GHz**



Date: 3.APR.2018 23:03:45




Plot on Configuration VHT80 / 5610 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 3 APR 2018 22:25:15


Plot on Configuration VHT80 / 5610 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 3 APR 2018 22:44:00




**Plot on Configuration VHT80 / 5610 MHz / Peak / Port 3 / 1GHz~3GHz**




Date: 3.APR.2018 22:46:11

**Plot on Configuration VHT80 / 5610 MHz / Peak / Port 4 / 1GHz~3GHz**




Date: 3.APR.2018 23:04:48

**Plot on Configuration VHT80 / 5690 MHz / Average / Port 1 / 1GHz~3GHz**




Date: 3.APR.2018 23:07:05

**Plot on Configuration VHT80 / 5690 MHz / Average / Port 2 / 1GHz~3GHz**




Date: 3.APR.2018 23:17:36

**Plot on Configuration VHT80 / 5690 MHz / Average / Port 3 / 1GHz~3GHz**



Date: 3.APR.2018 23:19:50


**Plot on Configuration VHT80 / 5690 MHz / Average / Port 4 / 1GHz~3GHz**



Date: 3.APR.2018 23:40:04




Plot on Configuration VHT80 / 5690 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 3.APR.2018 23:08:16


Plot on Configuration VHT80 / 5690 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 3.APR.2018 23:18:17




Plot on Configuration VHT80 / 5690 MHz / Peak / Port 3 / 1GHz~3GHz



Date: 3.APR.2018 23:20:43

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 4 / 1GHz~3GHz



Date: 3.APR.2018 23:41:29

**Plot on Configuration VHT20 / 5260 MHz / Average / Port 1 / 3GHz~6GHz**



Date: 3 APR 2018 23:59:20

**Plot on Configuration VHT20 / 5260 MHz / Average / Port 2 / 3GHz~6GHz**




Date: 4 APR 2018 00:35:01

**Plot on Configuration VHT20 / 5260 MHz / Average / Port 3 / 3GHz~6GHz**




Date: 4 APR 2018 00:43:14

**Plot on Configuration VHT20 / 5260 MHz / Average / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 00:52:18

**Plot on Configuration VHT20 / 5260 MHz / Peak / Port 1 / 3GHz~6GHz**



Date: 4 APR. 2018 00:01:01


**Plot on Configuration VHT20 / 5260 MHz / Peak / Port 2 / 3GHz~6GHz**



Date: 4 APR. 2018 00:36:41




**Plot on Configuration VHT20 / 5260 MHz / Peak / Port 3 / 3GHz~6GHz**



Date: 4 APR 2018 00:45:44

**Plot on Configuration VHT20 / 5260 MHz / Peak / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 00:53:30

**Plot on Configuration VHT20 / 5300 MHz / Average / Port 1 / 3GHz~6GHz**




Date: 4 APR 2018 00:59:52

**Plot on Configuration VHT20 / 5300 MHz / Average / Port 2 / 3GHz~6GHz**




Date: 4 APR 2018 01:07:08

**Plot on Configuration VHT20 / 5300 MHz / Average / Port 3 / 3GHz~6GHz**




Date: 4 APR.2018 01:13:54

**Plot on Configuration VHT20 / 5300 MHz / Average / Port 4 / 3GHz~6GHz**




Date: 4 APR.2018 01:23:43

**Plot on Configuration VHT20 / 5300 MHz / Peak / Port 1 / 3GHz~6GHz**




Date: 4 APR, 2018 01:00:30

**Plot on Configuration VHT20 / 5300 MHz / Peak / Port 2 / 3GHz~6GHz**




Date: 4 APR, 2018 01:08:21

**Plot on Configuration VHT20 / 5300 MHz / Peak / Port 3 / 3GHz~6GHz**




Date: 4 APR 2018 01:16:56

**Plot on Configuration VHT20 / 5300 MHz / Peak / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 01:24:48

**Plot on Configuration VHT20 / 5320 MHz / Average / Port 1 / 3GHz~6GHz**




Date: 4 APR 2018 01:30:46

**Plot on Configuration VHT20 / 5320 MHz / Average / Port 2 / 3GHz~6GHz**




Date: 4 APR 2018 01:36:38

**Plot on Configuration VHT20 / 5320 MHz / Average / Port 3 / 3GHz~6GHz**




Date: 4 APR 2018 01:44:17

**Plot on Configuration VHT20 / 5320 MHz / Average / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 01:51:17

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 4 APR 2018 01:31:26


Plot on Configuration VHT20 / 5320 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 4 APR 2018 01:37:22




**Plot on Configuration VHT20 / 5320 MHz / Peak / Port 3 / 3GHz~6GHz**




Date: 4 APR.2018 01:45:02

**Plot on Configuration VHT20 / 5320 MHz / Peak / Port 4 / 3GHz~6GHz**



Date: 4 APR.2018 01:52:48

Plot on Configuration VHT40 / 5270 MHz / Average / Port 1 / 3GHz~6GHz



Date: 4 APR 2018 01:59:31

Plot on Configuration VHT40 / 5270 MHz / Average / Port 2 / 3GHz~6GHz



Date: 4 APR 2018 02:05:28

**Plot on Configuration VHT40 / 5270 MHz / Average / Port 3 / 3GHz~6GHz**



Date: 4 APR, 2018 02:15:31


**Plot on Configuration VHT40 / 5270 MHz / Average / Port 4 / 3GHz~6GHz**



Date: 4 APR, 2018 02:24:09




Plot on Configuration VHT40 / 5270 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 4 APR, 2018 02:00:35

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 4 APR, 2018 02:08:16

**Plot on Configuration VHT40 / 5270 MHz / Peak / Port 3 / 3GHz~6GHz**




Date: 4 APR 2018 02:16:12

**Plot on Configuration VHT40 / 5270 MHz / Peak / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 02:25:23

**Plot on Configuration VHT40 / 5310 MHz / Average / Port 1 / 3GHz~6GHz**




Date: 4 APR, 2018 02:30:30

**Plot on Configuration VHT40 / 5310 MHz / Average / Port 2 / 3GHz~6GHz**




Date: 4 APR, 2018 02:35:57

**Plot on Configuration VHT40 / 5310 MHz / Average / Port 3 / 3GHz~6GHz**




Date: 4 APR 2018 02:40:54

**Plot on Configuration VHT40 / 5310 MHz / Average / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 02:46:47

**Plot on Configuration VHT40 / 5310 MHz / Peak / Port 1 / 3GHz~6GHz**



Date: 4 APR 2018 02:31:13


**Plot on Configuration VHT40 / 5310 MHz / Peak / Port 2 / 3GHz~6GHz**



Date: 4 APR 2018 02:36:33




**Plot on Configuration VHT40 / 5310 MHz / Peak / Port 3 / 3GHz~6GHz**




Date: 4 APR 2018 02:41:38

**Plot on Configuration VHT40 / 5310 MHz / Peak / Port 4 / 3GHz~6GHz**




Date: 4 APR 2018 02:47:31

**Plot on Configuration VHT80 / 5290 MHz / Average / Port 1 / 3GHz~6GHz**




Date: 6.APR.2018 20:15:34

**Plot on Configuration VHT80 / 5290 MHz / Average / Port 2 / 3GHz~6GHz**




Date: 6.APR.2018 20:24:37

**Plot on Configuration VHT80 / 5290 MHz / Average / Port 3 / 3GHz~6GHz**




Date: 6 APR 2018 20:32:59

**Plot on Configuration VHT80 / 5290 MHz / Average / Port 4 / 3GHz~6GHz**




Date: 6 APR 2018 20:44:07

**Plot on Configuration VHT80 / 5290 MHz / Peak / Port 1 / 3GHz~6GHz**




Date: 6 APR 2018 20:16:54

**Plot on Configuration VHT80 / 5290 MHz / Peak / Port 2 / 3GHz~6GHz**




Date: 6 APR 2018 20:25:30

**Plot on Configuration VHT80 / 5290 MHz / Peak / Port 3 / 3GHz~6GHz**



Date: 6.APR.2018 20:35:57

**Plot on Configuration VHT80 / 5290 MHz / Peak / Port 4 / 3GHz~6GHz**




Date: 6.APR.2018 20:45:27

**Plot on Configuration VHT20 / 5500 MHz / Average / Port 1 / 3GHz~6GHz**



Date: 31.MAR.2018 22:29:35

**Plot on Configuration VHT20 / 5500 MHz / Average / Port 2 / 3GHz~6GHz**




Date: 31.MAR.2018 22:37:30

**Plot on Configuration VHT20 / 5500 MHz / Average / Port 3 / 3GHz~6GHz**



Date: 31.MAR.2018 22:45:12

**Plot on Configuration VHT20 / 5500 MHz / Average / Port 4 / 3GHz~6GHz**



Date: 31.MAR.2018 22:55:48