Corporativo Lanix S.A. de C.V.

Carrtera internacional Hermosillo-Nogale Km 8.5, Hermosillo Sonora, Mexico

Date: April 15, 2016

## **Declaration**

To whom it may concern,

This is a WLAN/Bluetooth combination antenna with FCC ID: ZC4LT510. This WLAN/Bluetooth co-existence mechanism is to ensure that the WLAN and Bluetooth transmitters would not simultaneously operate. Therefore, WLAN and Bluetooth antenna in FCC ID: ZC4LT510 should not be considered to be able to transmit simultaneously.

Though the users can use WLAN and Bluetooth simultaneously, but the real situation is that WLAN and Bluetooth are used by time sharing and no overlap transmission.

Should you have any question, please have my best attention.

Sincerely yours,

Oscar Guzman / Product Manager

Corporativo Lanix S.A. de C.V. Tel: 6621090800

Fax: 6621090848

E-mail: oguzman@lanix.com

CORPORATIVO I ANIX. 5.A. DF. C.V.

CORPORATIVO I ANIX. 5.A. DF. C.V.

CARRET. INTERNALES KM. 1.3.

HERMOSIL LOS 08 00 FAX: 101-018.

HERMOSIL 109-08-00 00-LZ5

TEL 01(662) 109-08-00-08-LZ5