



11th April, 2011

buddi Limited
Kingfisher House, Walton Street
HP21 7AY Aylesbury

Re: FCC certification of buddi Madrid v8.3, ISM and GSM transmitter operation

To Whom It May Concern:

Buddi has designed the buddi Madrid v8.3 tracking device in such a way that both transceivers: ISM 914MHz and GSM never transmit at the same time. The ISM transmitter is normally used for a few milliseconds to interrogate proximity of a local beacon, before the ISM transceiver is used the GSM modem output is disabled by a software command and it will only be reinstated after the ISM protocol exchange is completed.

If you would like additional information about the implementation of this feature, don't hesitate to contact us.

Yours sincerely,

Jose A. Sanchez
Chief Technology Officer
buddi Limited
Kingfisher House, Walton Street
Aylesbury (Bucks) HP21 7AY
l: +44(0) 1296 468567 (direct)
m: +44(0) 7860 575830
e: jose@buddi.co.uk

www.buddi.co.uk

Tel: 0871 423 8756
www.buddi.co.uk
Co. Reg. No. 05308826

buddi Ltd, Kingfisher House
Walton Street, Aylesbury
Buckinghamshire HP21 7AY