

8. SETUP PHOTOS


RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






UL VERIFICATION SERVICES INC. FORM NO: CCSUP4701J 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.


RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







Page 81 of 84


RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION







Page 82 of 84





Page 83 of 84





END OF REPORT

 Page 84 of 84

 UL VERIFICATION SERVICES INC.
 FORM NO: CCSUP4701J

 47173 BENICIA STREET, FREMONT, CA 94538, USA
 TEL: (510) 771-1000
 FAX: (510) 661-0888

47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.