

## 11. SETUP PHOTOS


#### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



#### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)

Page 81 of 86







UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Page 82 of 86


#### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







Page 83 of 86

#### **RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION**






Page 84 of 86



### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



Page 85 of 86



# **END OF REPORT**

UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Page 86 of 86