

## 11. SETUP PHOTOS


#### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




Page 81 of 87




### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)



Page 82 of 87



#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION



Page 83 of 87





Page 84 of 87







Page 85 of 87



#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



Page 86 of 87



# **END OF REPORT**

UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Page 87 of 87