

# 11. SETUP PHOTOS


#### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



Page 56 of 62


## RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






Page 57 of 62


### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







Page 58 of 62

#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION






Page 59 of 62




UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Page 60 of 62

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





# **END OF REPORT**

Page 61 of 62

Page 62 of 62