

## 9. SETUP PHOTOS

#### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




Page 57 of 68




Page 58 of 68

### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)




Page 59 of 68




Page 60 of 68


#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




Page 61 of 68




Page 62 of 68




Page 63 of 68



Page 64 of 68




Page 65 of 68




Page 66 of 68

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



Page 67 of 68



# END OF REPORT

Page 68 of 68