
## **10. SETUP PHOTOS**

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




COMPLIANCE CERTIFICATION SERVICES (UL CCS)FORM NO: CCSUP4701D47173 BENICIA STREET, FREMONT, CA 94538, USATEL: (510) 771-1000FAX: (510) 661-0888This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 102 of 106


#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION





Page 103 of 106


COMPLIANCE CERTIFICATION SERVICES (UL CCS)FORM NO: CCSUP4701D47173 BENICIA STREET, FREMONT, CA 94538, USATEL: (510) 771-1000FAX: (510) 661-0888This report shall not be reproduced except in full, without the written approval of UL CCS.





Page 104 of 106






Page 105 of 106

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





# **END OF REPORT**

Page 106 of 106

COMPLIANCE CERTIFICATION SERVICES (UL CCS)FORM NO: CCSUP4701D47173 BENICIA STREET, FREMONT, CA 94538, USATEL: (510) 771-1000FAX: (510) 661-0888This report shall not be reproduced except in full, without the written approval of UL CCS.