Report No.: 12U14516-7 Issue Date: 8/15/12 FCC ID: ZNFP769

16. External Photos






Rear View





17. Antenna Locations & Separation Distances



Report No.: 12U14516-7 Issue Date: 8/15/12 FCC ID: ZNFP769


18. **Setup Photos**






Report No.: 12U14516-7 Issue Date: 8/15/12 FCC ID: ZNFP769


Right Hand Side Touch



Right Hand Side Tilt (15°)



FORM NO: CCSUP4031G








FORM NO: CCSUP4031G

ENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.




Body&Hotspot - Edge1 w/ 10 mm Separation



FORM NO: CCSUP4031G

ENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Body&Hotspot - Edge2 w/ 10 mm Separation





FORM NO: CCSUP4031G

ENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Report No.: 12U14516-7 Issue Date: 8/15/12 FCC ID: ZNFP769



END OF REPORT

47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.