
9. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



UL CCS FORM NO: CCSUP4701F 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.


Page 52 of 59

RADIATED RF MEASUREMENT SETUP



UL CCS FORM NO: CCSUP4701F 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 53 of 59




Page 54 of 59

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




UL CCS FORM NO: CCSUP4701F 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 55 of 59




Page 56 of 59




Page 57 of 59

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



UL CCS FORM NO: CCSUP4701F 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 58 of 59



END OF REPORT

UL CCS FORM NO: CCSUP4701F 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 59 of 59