

3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0500 Page (27) of (31)

APPENDIX B - Test Setup Photos and Configuration

Conducted Emissions at Mains Power Ports

■ Charge Mode









3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0500 Page (28) of (31)

Radiated Electric Field Emissions(Below 1 6 ₪)

■ Charge Mode









3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0500 Page (29) of (31)

■ Operating Mode









3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0500 Page (30) of (31)

Radiated Electric Field Emissions(Above 1 € 12)

■ Charge Mode







3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0500 Page (31) of (31)

■ Operating Mode

