


Product Conformance Statement

We Guangzhou Fantasia Creation Toys Co. Ltd., after the test from Bureau Veritas Consumer Products Services –Dongguan, our product ROVER II was unqualified. The modification plan provided by BVDG's engineer is as follows: The DC input should add a Common Mode Inductor and a 104 Capacitor. 2J1 together with 2J2 add a magnetic ring (16*8*12) and run a round around, C-MOS run a round around a magnetic ring (25*10*15.7), J1 and J2 append a magnetic ring respectively, the material number is 16*8*12, RF connecting line should append a magnetic ring and run two rounds around magnetic ring (16*8*12.). In the PCB board should add a piece of copper grounding. 1J1&1J2 signal lines should increase by 100P capacitor to ground, 2J1&2J2 motor output should increase by 104 capacitor to ground, change all 22 ohms Resistance 180 ohms.

We hereby declare: Our company will be in accordance with this scheme to produce all products.

Company Name: Guangzhou Fantasia Creation Toys Co. Ltd.,

Person in charge:  2012.7.18

Date: 2012-7-18