Ambitio LLC, The Owner of unnecto ™ Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Comparison Information

FCC ID: ZU31	Model Name:	Produce Information
ZU3UNNECTOECO	U-100-2	Old
ZU3UNNECTOECO2	U-100-2	New

									į	7
		Þ	2	RES, 10 OHM 0402 ±5%, 50V	90116000800	R302 R315		-	16	Note:
		Α	2	90116000500 RES,0 OHM 0402 ±5%, 50V	90116000500	R313 R429			15	
		А	1	CAP 0603 1u 80/-20% 10V	90117004700	C507	\perp		14	
		A	2	90117005700 CAP 0402 1u 6.3V ±10%	90117005700	C512 C511			+	
		Α	1	90116003500 RES,47KOHM 0402 ±5%, 50V	90116003500	R501		L	+	L
		Α	_	CAP 0402 56p 50V ±5%	90117002600	C513		Ľ	-	[.
		Α	_	Bluetooth IC:MT6622	90104005425	U503		_	10	
tunction	.1630	Α	1	MT6622_BPF,RFBPB2012090AM1T61	90106014425	U502		L	9	Т
	USA_EN_1.00	А	1	90116006400 RES,15KOHM 0402 ±5%, 50V	90116006400	R504			0	Г
Need to add bluetooth		Α	_	90117003700 CAP 0402 1nF 50V ±5%	90117003700	C515		_	7	Τ
	> > > > > > > > > > > > > > > > > > > >	Α	_	二极管,1SS400TE61	90119000400	D100		-	6	
		Α	4	90117004000 CAP 0402 0.1uF 16V +/-20%	90117004000	C702 C508 C509 C510			5	
		Α	_	90120000525 PNP三极管,FJY4002R	90120000525	U303		Ľ	4	
		Α	2	90116004000 RES,100KOHM 0402 ±5%, 50V	90116004000	R314 R100		Ľ	ω	Т
		А	ω	RES,10 OHM 0402 ±5%, 50V	90116000800	R312 R316 R300			2	
	The second secon	-				R511		H	H	H
		Α	5	RES,0 OHM 0402 ±5%, 50V	90116000500	R428 C514 R502 R505		ŀ		
Change Reason	Change Model	Class	Q'ty	Description	PART NO	Part	Delete Layer	Add Del	1	N _O
		DECO2	NECT	List of Differences for FCC ID: ZU3UNNECTOECO2						
										000000

The previous reports are still applicable reason

The Bluetooth module was added to this device. Shenzhen Super Test Service Technology Co., Ltd. perform proper testing on the Bluetooth Portion of the device on March 2,2012-March

There were no change on the RF Transmitter and RF Transmitter circuitry of the GSM Portion of the device is as the same as the old original, so we do not have to perform testing on its GSM Portion

I would like to confirm that above changes would influence to the Bluetooth of the device. Therefore, we would submit the Test Report for its bluetooth. Portion with its test Reports.

Sincerely

Ambitio LLC, The Owner of unnecto ™
<SIGNATURE of Daniel Moy>

Daniel Moy (Manager)

Date: Augutst 04,2012