



TCL通力电子(惠州)有限公司
惠州 TCL 音视频电子有限公司
深圳市通力科技开发有限公司

序号:

表格编号: TCLAV-A4-2004003

版本: V1.4

表格修订日期: 2014-04-08

拟制日期: 2011-6-1

Request for Class II Permissive Change

FCC ID: ZVA06

Data: November 27, 2014

TO: Federal Communication Commission

Please be notified that we, the undersigned, **TCL TECHNOLOGY ELECTRONICS (HUIZHOU) CO., LTD** declare that the reasons for this reassessment are as below:

The module (BM63) keep the original, but the external Schematics had changed, the following are the major difference:

1. SRS-X55's Power supply is different from SRS-33
2. Audio amplifier is different
3. Charge IC is different
4. SRS-X55 have DC_DC down circuit which use for 5V voltage output, but SRS-33 have not.
5. SRS-55 have touch IC but SRS-X33 have not.

Thank you.
Sincerely,

Weirun, Peng
Approbation Engineer
TCL Technoly Electronics (Huizhou) Co.,Ltd
Tel: 0752-3270717
Web site: www.tonlvele.com
E-mail: gongxh@tcl.com