



FCC ID: ZVS-NVX-610
Device Name: VoIP Phone
Model No.: NVX 610

Date: 10/5/2011

Federal Communications Commission

Dear Sir:

Pursuant to Section 0.457 and 0.459 of the Commission's Rules, the Applicant hereby requests confidential treatment of information accompanying this Application as outlined below:

Schematics
Block Diagram
Operational Descriptions

The above materials contain trade secrets and proprietary information not customarily released to the public. The public disclosure of these matters might be harmful to the Applicant and provide unjustified benefits to its competitors.

The Applicant understands that pursuant to Rule 0.457, disclosure of this Application and all accompanying documentation will not be made before the date of the Grant for this application.

Sincerely Yours,

By:

Pierre Emerich

Title : Project Manager
Applicant : invoxia
Address : 87 Rue Du Gouverneur General Eboue, 92130, Issy-Les-Moulineaux, France
Tel : +33 1 41 09 97 43
Fax: +33 1 46 44 51 54

操作手冊

(1)操作手冊內必須要有下述說明

The changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.


To comply with the FCC RF exposure compliance requirements, this device and its antenna must not be co-located or operating to conjunction with any other antenna or transmitter.

(2)若為數位產品或周邊(Digital Device or Peripheral) 請另外加上如下說明

Note: This equipment has been tested and found to comply with the limits for a Class B Digital Device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instruction, may cause harmful interference to radio communication. However, there is no grantee that interference will not occur in a particular installation. If this equipment dose cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on , the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.


貼於產品本體之標籤圖解範例



註：如果產品太小（如：小於一個手掌之大小）而無法製作如此多文字的標籤，則只需要在標籤上註明 FCC ID 號碼，而將上述文字說明印在使用手冊上。

ID Label 之要求如下：

1. 請註明將貼於產品何處（需為明顯易見處）
2. 標籤上請註明產品 FCC ID 號碼
3. 行數及長寬形狀可依實際製作之標籤大小調整(參考範例)：



000：表示 FCC Grantee Code (為公司代碼，須先向 FCC 申請)

XXXXXXXXXXXX：表示產品代碼 (Product Code)，廠商可自行選定 (14 碼以內，可為數字或大寫英文字母或“-”，不可空格、逗號或其它特殊符號。)