

Chris Harvey

From: Claire Hoque
Sent: Tuesday, May 25, 2004 1:35 PM
To: Chris Harvey
Cc: Mike Kuo; Michael Heckrotte; Helen Zhao
Subject: RE: Additional Information needed AN04T3874 FCC ID: BEJLSI110



Class II Permissive
Change.zip...

Hi Chris,

LG has changed the submission scopes from new submission to Class II change submission. The Class II submission package(also attached in this email)is saved in TCB upload drive: F:\upload\AN04T3874\Class II submission

731 form is also modified.
Pls kindly review the package.
Thanks,

Claire

-----Original Message-----

From: Chris Harvey
Sent: Wednesday, May 19, 2004 3:53 PM
To: Michael Heckrotte; Chris Harvey
Cc: Mike Kuo; Claire Hoque
Subject: RE: Additional Information needed AN04T3874 FCC ID: BEJLSI110

This is just a 'ping' to see if there is any activity on this application. As far as I can tell this was the last communication regarding this application.

Thanks,

Chris

-----Original Message-----

From: Chris Harvey [mailto:Chrisharveyemc@comcast.net]
Sent: Friday, April 30, 2004 4:56 PM
To: 'Michael Heckrotte'; 'Chris Harvey'
Cc: 'Mike Kuo'; 'Claire Hoque'
Subject: RE: Additional Information needed AN04T3874 FCC ID: BEJLSI110

Michael, usually there is some description of the emission designator, which satisfies the 2.1033 requirement, but I actually neglected to go to the Form 731 for this application (this is sufficient for this application.) Consider item#1 closed.

Chris

-----Original Message-----

From: Michael Heckrotte [mailto:MHeckrotte@CCSEMC.com]
Sent: Friday, April 30, 2004 5:19 PM
To: Chris Harvey
Cc: Mike Kuo; Claire Hoque

Subject: RE: Additional Information needed AN04T3874 FCC ID: BEJLSI110

Chris,

Regarding #1, the emission designator was included on the Form 731 as 1M28F9W, based on page 13 of the test report. Is there some other document that is missing the emission designator or has an incorrect emission designator?

Thanks,
Mike

-----Original Message-----

From: Chris Harvey
Sent: Friday, April 30, 2004 12:23 PM
To: Michael Heckrotte
Cc: Mike Kuo; Chris Harvey
Subject: FW: Additional Information needed AN04T3874 FCC ID: BEJLSI110

Michael,

The above referenced application has been reviewed and the following items need to be addressed so that processing can continue:

1. Please provide the description of the Emission Designator for this CDMA handset. (It is likely to be 1M25F9W, but please state this and explain.)
2. This application was filed as a 'Original Equipment' however the FCC ID: BEJLSI110 was previously granted in July 2002. If this is a Class II Permissive Change application, please provide an exhibit requesting a Permissive Change to this product, explaining the difference between this device and the previously granted device (please see FCC 2.1043). If this is a new application for Original Equipment, please provide a new, original FCC ID number and corrected exhibits that contain the FCC ID number.
3. One of the exhibits submitted for this application is for MPE calculation of a 2.4GHz device (file name FD-09101746-0 RF Exposure.pdf). Since this device is an 850MHz Portable handset, this exhibit appears to be not applicable. Please confirm that this exhibit was not intended to be provided for this application.
4. Please provide a more detailed description of the CDMA modulation to satisfy the requirements of FCC 2.1033.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Please provide this information directly to me.

Best regards,

Chris Harvey
Charvey-tcb@ccsemc.com