




Test Date	2017/11/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
		Frequency	TX 5190MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT80	






Test Date	2017/11/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
		Frequency	TX 5230MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT80	







Test Date	2017/11/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	3dB	Frequency	TX 5270MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT803	





Test Date	2017/11/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
		Frequency	TX 5310MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT80	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
 Fax: +886 2 26099303

Test Date	2017/11/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5510MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT80	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/11/28	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	3dB	Frequency	TX 5550MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V/60HZ (via AC Adapter)
		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT803	







Test Date	2017/11/28	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5670MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT803	





Test Date	2017/11/28	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5710MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT803	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/11/29	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	III
		Frequency	TX 5755MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT803	





Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
 Fax: +886 2 26099303

Test Date	2017/11/28	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	III
		Frequency	TX 5795MHz
Cable Loss	3dB	Test Voltage	AC 120V/60HZ (via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0 for 802.11a, 3 for 802.11n-HT20/40 and 802.11ac-VHT803	

