

RF emission

1) Please readdress the FCC 3G policy. Please include details of the device's capabilities and description of process to select subsets for testing.

[Please find attached updated HAC Test Report with capabilities and investigation used to select subset for testing on Page 20.](#)

2) Please detail device configuration used for the "CDMA" probe modulation factor on page 19 of 66.

[Please find attached updated HAC Test Report with device configuration used on Page 19.](#)

T-coil rating

3) Please readdress the FCC 3G policy. Please include details of the device's capabilities and description of process to select subsets for testing.

[Please find attached updated HAC Test Report with capabilities and investigation used to select subset for testing on Page 23.](#)

4) Please provide ambient noise for both ABM1 and ABM2.

[Please find attached updated HAC Test Report with ambient noise data on Page 20.](#)

5) It appears that the T-coil is offset from the speaker. The RF scan should be made centered on the T-coil. Please readdress the RF T-coil emission category. Please provide test data with the scan properly centered.

[Please find attached updated HAC Test Report with RF scan centered on the T-coil data on Page 21-22.](#)