

FUNCTIONAL DESCRIPTION

The 5882AP is a 315 MHz version of our 5882-4 receiver;(FCC ID: CFS8DL5882-4) it is identical in function and operation with the exception of the operating frequency which is 315 MHz. to allow reception of our 315 MHz transmitters such as the CFS8DL5816AP, and CFS8DL5804AP, etc.