Label



191 Airport Boulevard Burlingame, CA 94010 1-888-TANGENT www.tangent.com

FCC ID: II70EM-805N21XU Contains FCC ID: II7AX210NG





MEDICAL EQUIPMENT WITH RESPECT TO ELECTRIC SHOCK FIRE AND MECHANICAL HAZARDS ONLY IN ACCORDANCE WITH ANSI/AAMI ES60601-1 AND CAN/CAS-C22

No 60601-1

LISTED



Part number: XXXXXXXXXXXXX Input: 19V -- 4.74A

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired

operation.

Made in Taiwan

Label location

LISTED

