



Please refer to following plots:

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3555MHz_DFT-s-OFDM QPSK_RB0RB1@0




Date: 25.FEB.2023 21:22:27

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3555MHz_DFT-s-OFDM QPSK_RB0RB1@0




Date: 25.FEB.2023 11:41:19

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3555MHz_DFT-s-OFDM QPSK_RB0RB24@0




Date: 25.FEB.2023 20:43:05

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3555MHz_DFT-s-OFDM QPSK_RB0RB24@0




Date: 25.FEB.2023 20:53:43

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3624.99MHz_DFT-s-OFDM QPSK_RB0RB24@0




Date: 25.FEB.2023 20:47:52

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3624.99MHz_DFT-s-OFDM QPSK_RB0RB24@0




Date: 25.FEB.2023 20:46:22

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3694.98MHz_DFT-s-OFDM QPSK_RB0RB1@23




Date: 25.FEB.2023 20:52:34

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3694.98MHz_DFT-s-OFDM QPSK_RB0RB1@23




Date: 25.FEB.2023 20:51:25

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3694.98MHz_DFT-s-OFDM QPSK_RB0RB24@0




Date: 25.FEB.2023 20:49:30

DC_5A_n48A_10MHz10MHz_30kHz_836.5MHz3694.98MHz_DFT-s-OFDM QPSK_RB0RB24@0




Date: 25.FEB.2023 20:50:41

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3560.01MHz_DFT-s-OFDM QPSK_RB0RB1@0




Date: 25.FEB.2023 20:59:14

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3560.01MHz_DFT-s-OFDM QPSK_RB0RB1@0




Date: 25.FEB.2023 20:58:18

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3560.01MHz_DFT-s-OFDM QPSK_RB0RB50@0




Date: 25.FEB.2023 20:55:54

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3560.01MHz_DFT-s-OFDM QPSK_RB0RB50@0




Date: 25.FEB.2023 20:56:44

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3624.99MHz_DFT-s-OFDM QPSK_RB0RB50@0




Date: 25.FEB.2023 21:00:48

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3624.99MHz_DFT-s-OFDM QPSK_RB0RB50@0




Date: 25.FEB.2023 21:01:50

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3684.99MHz_DFT-s-OFDM QPSK_RB0RB1@50




Date: 25.FEB.2023 21:05:18

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3684.99MHz_DFT-s-OFDM QPSK_RB0RB1@50




Date: 25.FEB.2023 21:06:35

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3684.99MHz_DFT-s-OFDM QPSK_RB0RB50@0




Date: 25.FEB.2023 21:04:01

DC_5A_n48A_10MHz20MHz_30kHz_836.5MHz3684.99MHz_DFT-s-OFDM QPSK_RB0RB50@0




Date: 25.FEB.2023 21:03:04

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3570MHz_DFT-s-OFDM QPSK_RB0RB1@0




Date: 25.FEB.2023 21:09:47

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3570MHz_DFT-s-OFDM QPSK_RB0RB1@0




Date: 25.FEB.2023 21:10:27

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3570MHz_DFT-s-OFDM QPSK_RB0RB100@0




Date: 25.FEB.2023 21:08:44

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3570MHz_DFT-s-OFDM QPSK_RB0RB100@0




Date: 25.FEB.2023 21:08:04

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3624.99MHz_DFT-s-OFDM QPSK_RB0RB100@0




Date: 25.FEB.2023 21:12:15

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3624.99MHz_DFT-s-OFDM QPSK_RB0RB100@0




Date: 25.FEB.2023 21:11:29

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3679.98MHz_DFT-s-OFDM QPSK_RB0RB1@105




Date: 25.FEB.2023 21:16:56

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3679.98MHz_DFT-s-OFDM QPSK_RB0RB1@105




Date: 25.FEB.2023 21:16:16

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3679.98MHz_DFT-s-OFDM QPSK_RB0RB100@0



Date: 25.FEB.2023 21:14:23

DC_5A_n48A_10MHz40MHz_30kHz_836.5MHz3679.98MHz_DFT-s-OFDM QPSK_RB0RB100@0



Date: 25.FEB.2023 21:15:24