

July 15, 2020

Ms. Marlene H. Dortch Secretary Federal Communications Commission 445 12th Street, S.W. Washington, D.C. 20554

Re: Request for Further Extension of Special Temporary Authority to Operate Galaxy 12 at 129.0° W.L. with New Beam Coverage; Call Sign: S2422

Dear Ms. Dortch:

Intelsat License LLC, as debtor in possession ("Intelsat"), herein requests an additional 30 days of Special Temporary Authority ("STA")¹ previously granted to Intelsat² to operate the Galaxy 12 satellite's (Call Sign S2422) C-band beams over a new coverage area in the communications frequencies 3700-4200 MHz in order to provide customer service. The beams will bias on a seasonal basis, and Intelsat will be filing a license modification application to support this new service area. The coverage requested herein is to continue winter operations. Intelsat incorporates by reference Exhibit A of its original request,³ which contains maps of the new coverage areas.

Galaxy 12 is permanently licensed to operate at 129.0° W.L. with different C-band beam coverage than proposed herein.⁴ Intelsat is biasing the satellite's C-band beams in order to achieve the desired winter coverage area.⁵ Intelsat's continued operation of Galaxy 12 will conform to existing coordination agreements and the Federal Communications Commission's ("Commission") rules governing operations vis-à-vis adjacent locations.

The continued temporary operation of the satellite's C-band beams with different coverage than authorized by its current license will allow Intelsat to meet customer demand for service while it seeks permanent authority. Accordingly, grant of this further STA extension request is in the public interest.

¹ Intelsat has filed this STA request, an FCC Form 159, and a \$980.00 filing fee electronically via the International Bureau's Filing System.

² See, e.g., Satellite Policy Branch Information; Actions Taken, Report No. SAT-01477, File No. SAT-STA-20200615-00077 (June 26, 2020) (Public Notice).

³ See Satellite Policy Branch Information; Actions Taken, Report No. SAT-01429, File No. SAT-STA-20191002-00106 (Nov. 22, 2019) (Public Notice).

⁴ See Policy Branch Information, Actions Taken, Report No. SAT-01311, File No. SAT-MOD-20180215-00017 (April 20, 2018) (Public Notice).

⁵ Galaxy 12 only has two beams—the North America H Beam and the North America V Beam.

Intelsat US LLC 7900 Tysons One Place, McLean, VA 22102-5972 USA | T +1 703-559-6800 | www.intelsat.com Ms. Marlene H. Dortch July 15, 2020 Page 2

For the reasons set forth herein, Intelsat respectfully requests that the Commission grant this further STA extension request. Please direct any questions with regard to this request to the undersigned at (703) 559-6949.

Sincerely,

<u>/s/ Cynthia J. Grady</u> Cynthia J. Grady Senior Counsel Intelsat US LLC

cc: Jay Whaley Jennifer Balatan