

PURPOSE OF FURTHER AMENDMENT

Telesat Network Services, Inc. hereby further amends its pending application to modify its license for Call Sign E030029 (File Nos. SES-MOD-20150701-00437 and SES-AMD-20151105-00815) to make the following technical changes:

- The 8M79G7W carrier (Line #159) is being updated to correct the EIRP to **69.5 dBW**, as reflected on the Schedule 312-B submitted with this amendment.
- The carrier for 13.77-13.78 GHz (Line #163) is being updated to change the carrier emission to **4M00G7W** and to correct the EIRP to **69.2 dBW**, as reflected on the Schedule 312-B submitted with this amendment.
- The 600KG7W carrier for 13.75-14.00 GHz (Line #164) should be deleted. In its place, Telesat respectfully requests that the carrier be separated into three sub-bands as follows and as reflected on the Schedule 312-B submitted with this amendment:
 - 13.75-13.77 GHz (600KG7W, 68.1 dBW EIRP)
 - 13.77-13.78 GHz (see Line #163; 4M00G7W, 69.2 dBW EIRP)
 - 13.78-14.00 GHz (600KG7W, 68.1 dBW EIRP)