

FREQUENCY COORDINATION REPORT

GCL Licensee LLC provided the required frequency coordination report for the proposed feeder link earth station antenna in Las Palmas, Puerto Rico, in its July 28, 2020 application for modification of its authority under call sign E990037. *See* Application of GCL Licensee LLC, FCC File No. SES-LIC-20200728-00812, Response to FCC Form 312, Schedule B, Question E18: Comsearch Frequency Coordination and Interference Analysis Report (July 28, 2020). No further coordination report is required for the instant application amendment.