

MessageFrom: Shoemaker, Troy [troys Shoemaker@clearchannel.com]  
Sent: Tuesday, January 20, 2004 4:00 PM  
To: Towanda Bryant  
Subject: FW: File Number ses-lic-20040115-00052, E040036

Hello Again,

After talking to George, He advised that the EIRP, and EIRP density needed to be changed follow the change from 16 watts , to 4 watts.

So please change the EIRP(dBW) 61.24 to 55.22, and The EIRP Den. From 41.22 to 35.20.

Again thanks for letting me make theses changes on the fly.

Regards,  
Troy Shoemaker  
Clear Channel Satellite Services  
7042 So. Revere Parkway #450  
Englewood CO. 80112  
303 925 1708 Voice  
303 925 1714 Fax  
troys Shoemaker@clearchannel.com

-----Original Message-----

From: Towanda Bryant [mailto:Towanda.Bryant@fcc.gov]  
Sent: Tuesday, January 20, 2004 1:39 PM  
To: Shoemaker, Troy  
Subject: RE: File Number ses-lic-20040115-00052, E040036

Tnx. I have made the changes and we still have a problem with the power. I have faxed you the new check sheet. Please take a look and email me the changes.

Tnx. T.

-----Original Message-----

From: Shoemaker, Troy [mailto:troys Shoemaker@clearchannel.com]  
Sent: Tuesday, January 20, 2004 3:25 PM  
To: Towanda Bryant  
Cc: Shoemaker, Troy  
Subject: File Number ses-lic-20040115-00052, E040036

Hello Towanda,

I received your E-mail advising of the changes needed to our license.

I accept the changes to the West Azim Angle from 225.4 to 224.9.

We also want to change the Max power input from 16 watts, to 4 Watts. Which should lower the power density to within the parameters.

I hope this e-mail is all you need to make the changes. I tried to call your number of 202 418 1245. I was advised this was a wrong number.

Please let me know if you need any thing else.

Regards:

Troy Shoemaker

Clear Channel Satellite Services

7042 So. Revere Parkway #450

Englewood CO. 80112

303 925 1708 Voice

303 925 1714 Fax

[troyshoemaker@clearchannel.com](mailto:troyshoemaker@clearchannel.com)