

Towanda Bryant

From: Hunter, Daryl [daryl.hunter@viasat.com]
Sent: Thursday, August 04, 2011 3:37 PM
To: Towanda Bryant
Cc: Trang Nguyen
Subject: Re: SES-LIC-20110228-00212, E110026

Hi Towanda,

If I understand the output in the text attachment in your email correctly, it is an Az/EI angle issue for the satellite on the Eastern limit.

My apologies, this seems to be a data entry error. The numbers appear to be from the row beneath the Milford entry in my spreadsheet.

The correct angles should be as follows:

East Satellite Arc Limit = 41 W

East Az Limit = 101.44

East EI Limit = 5.38

Regards,

Daryl

Daryl T. Hunter, P.E.
Director, Regulatory Affairs
ViaSat, Inc.
6155 El Camino Real
Carlsbad, CA 92009
Email: daryl.hunter@viasat.com
Phone: 760-476-2583
Fax: 760-929-3934

ViaSat Brings Your Network to Life

[<www.viasat.com>](http://www.viasat.com)