

June 20, 2017

## VIA ELECTRONIC DELIVERY

Marlene H. Dortch, Secretary Federal Communications Commission 445 Twelfth Street, SW Washington, DC 20554

## Re: IBFS File No. SES-LIC-20160610-00541, Call Sign E160111

Dear Ms. Dortch:

Pursuant to condition 900402 in the above-referenced earth station antenna license, ViaSat submits the attached Comsearch report demonstrating that coordination has been completed.

This report satisfies the pre-operation condition in the license.

Please contact the undersigned with any questions.

Sincerely,

/s/ Steven C. Hemple Regulatory Engineer ViaSat, Inc. 19700 Janelia Farm Boulevard Ashburn, VA 20147 USA (703) 726-5500 Fax (703) 726-5600 www.comsearch.com



## Supplemental Showing Pursuant To: 28 Ghz Coordination Procedures

28 GHZ Coordination Procedures

## Reference: 170301COMSMS23 Viasat, Inc. Rapid City, SD (E160111)

On March 1, 2017 coordination data for the above referenced market was forwarded to all existing licensees and applicants whose facilities could be affected by the proposed system.

The following carriers or their designated coordination agents were notified, and there are no unresolved interference objections.

Licensees

Frontier Information Super Station

Respectfully Submitted,

COMSEARCH

/s/ Inderjeet Singh Electrical Engineer