

June 20, 2017

**VIA ELECTRONIC DELIVERY**

Marlene H. Dortch, Secretary  
Federal Communications Commission  
445 Twelfth Street, SW  
Washington, DC 20554

**Re: IBFS File No. SES-LIC-20160610-00549, Call Sign E160119**

Dear Ms. Dortch:

Pursuant to condition 900402 in the above-referenced earth station antenna license, ViaSat submits the attached Comsearch report demonstrating that coordination has been completed.

This report satisfies the pre-operation condition in the license.

Please contact the undersigned with any questions.

Sincerely,

/s/ Steven C. Hemple  
Regulatory Engineer  
ViaSat, Inc.

19700 Janelia Farm Boulevard  
Ashburn, VA 20147 USA  
(703) 726-5500  
Fax (703) 726-5600  
www.comsearch.com



**Supplemental Showing Pursuant To:  
28 Ghz Coordination Procedures**

**Reference:  
170301COMSMS31  
Viasat, Inc.  
Tornillo, TX (E160119)**

On March 1, 2017 coordination data for the above referenced market was forwarded to all existing licensees and applicants whose facilities could be affected by the proposed system.

The following carriers or their designated coordination agents were notified, and there are no unresolved interference objections.

Licensees

---

Frontier  
Information Super Station  
Verizon  
XO Communications

Respectfully Submitted,

COMSEARCH

/s/ Inderjeet Singh  
Electrical Engineer