

From: Charles W Pepin [Charles\_W\_Pepin@raytheon.com]  
Sent: Thursday, December 08, 2005 12:07 PM  
To: Towanda Bryant  
Subject: E030083 license Modification

Ms Bryant,

The modification is to add three additional antennas to the present operating system. The antennas will be exchanged as required. They will not be in operation at the same time. The same transmitter and receiver will be in operation will generate the source. The same correlated frequencies in operation for the 2.4 meter antenna will also be the frequencies utilized for the antennas added for the modification.

Charles W. Pepin  
EEEC/FCC Manager

Raytheon Company  
MS: EEEEC/FCC  
528 Boston Post Road  
Sudbury, Ma 01776

Tele. No. 978-440-2673  
RayNet: 7-431-2673  
Fax Number: 978-440-3332 (EEEC)