

---

*SES Americom, Inc.  
Four Research Way, Princeton, NJ 08540-6684*

January 27, 2009

Federal Communications Commission  
International Bureau  
445 12<sup>th</sup> Street S.W.  
Washington, DC 20554  
Attn: Ms. Marlene H. Dortch, Secretary

Attn.: Satellite Engineering Branch  
Satellite and Radiocommunications Division  
International Bureau

Re: E910548 3.7m Antenna

Dear Secretary Dortch:

SES Americom, Inc. has noticed that the 3.7m Global Star antenna that was applied to be added to Callsign E910548 in the August, 2007 modification application was incorrectly listed on the license as a 7.3m Global Star antenna (FCC File No. SES-MOD-20070705-00893). SES Americom, Inc. is requesting that the license be reissued with the correct 3.7m antenna listed on the license.

Thank you for your attention to this matter.

Sincerely,



David A. Barton  
Engineer, Ground Systems  
SES Americom, Inc.  
609-987-4133