

**ISAT US Inc.**  
**FCC Form 312**  
**Supplement to Modification Application**

Inmarsat can confirm that the BGAN 9202 will have a shut-off time of less than three seconds and, in fact, of less than one second. This should meet any shut-off standard that has been applied to date.

This filing incorporates by reference the detailed showing addressing compliance with Section 25.136(d) that Inmarsat made in its initial blanket license application. *See* Exhibit E, Section E of IBFS File No. SES-LIC-20090217-00184. That showing remains equally applicable to the BGAN 9202 and operations of the BGAN 9202 will comply with Section 25.136(d) requirements in the same manner.