

## Towanda Bryant

---

**From:** Brad Smith <Brad.Smith@globecast.com>  
**Sent:** Wednesday, April 29, 2015 12:17 PM  
**To:** Towanda Bryant  
**Subject:** SES-MOD-20150410-00208, KA222

Towanda

After further review re HPA Tx power versus power at the antenna flange the numbers below are correct for this antenna:

E38: 300W  
E40: 80 dBW

Regards

### **Brad Smith**

Engineering Manager – Transmission and Networks



Globecast Americas  
10525 West Washington Blvd.  
Culver City, CA 90232

**Tel:** +1 (310) 845-3881  
**Mob:** +1 (310) 339 7094

<http://globecast.com>

part of the Orange group

**Your channel in every format, every screen, every region.**

