



WASHINGTON, DC

DAVID S. KEIR  
202.416.6742  
DKEIR@LERMANCENTER.COM

October 23, 2017

**SUBMITTED VIA IBFS**

Ms. Marlene H. Dortch, Secretary  
Federal Communications Commission  
445 Twelfth Street, SW  
Washington, DC 20554

**Re: MTN License Corp., Modification Application,  
File No. SES-MOD-20171002-01087, Call Sign E990325,  
Clarification Letter Pursuant to Section 1.65 of the FCC's Rules**

Dear Ms. Dortch:

MTN License Corp. ("MTN") submits this letter in response to a request from the Satellite Division to clarify in two minor respects the modified authority that is requested in the above-referenced application.

First, the geographic coordinates contained in the current license are based on the NAD-27 datum. Please correct the coordinates in Section A of the modified license to the following, which are based on the NAD-83 datum:

40° 23' 40.44" North, 74° 10' 24.84" West


Second, the EIRP value level for both 36 MHz carriers (at 5925-6425 MHz and 5850-6425 MHz) was incorrectly stated at Line E48 of the initial application, and this value should be corrected in both instances to **80.47 dBW**.

LS

Ms. Marlene H. Dortch  
October 23, 2017  
Page 2

With these clarifications, we hope that you are able to place the application on Public Notice as accepted for filing. Of course, should there be any additional questions regarding the application, as clarified, please contact the undersigned counsel.

Respectfully submitted,



David S. Keir  
*Counsel to MPN License Corp.*

cc: Paul Blais (FCC)  
Trang Nguyen (FCC)  
Towanda Bryant (FCC)