

**Speedcast Communications, Inc., as a debtor-in-possession**  
**File No. SES-MOD-20170427-00475, SES-ASG-20200504-00482 and SES-RWL-\_\_\_\_\_**  
**Call Sign E050333 - Renewal of License**

**Attachment A – Additional Information**

Speedcast Communications, Inc., as a debtor-in-possession (“Speedcast”) is requesting renewal of the above-referenced license to ensure continuity of service to the customer location, the East Breaks 602 (“Nansen”) oil platform located in the Gulf of Mexico.

A Frequency Coordination Study was filed with the Nansen oil platform earth station in Speedcast’s most recent modification of the license.<sup>1</sup> After confirming with Comsearch, Speedcast hereby certifies that there are no 6 GHz terrestrial microwave links within the coordination contour of the earth station. Accordingly, there is no potential for unacceptable interference to such co-frequency operations, no additional coordination is needed, and this renewal application may be granted with the same operational characteristics and conditions included in the current license.

Should the renewal remain pending on the expiration date of the license, March 10, 2021, Speedcast understands that the filing of this renewal application will permit the license to continue in effect and thus provide authority to Speedcast to continue operating the associated earth station after the original expiration date of the license while the renewal is pending.<sup>2</sup>

---

<sup>1</sup> See File No. SES-MOD-20170427-00475.

<sup>2</sup> 47 C.F.R. § 1.62(a)(1) (providing that “[w]here there is pending before the Commission at the time of expiration of license any proper and timely application for renewal of license with respect to any activity of a continuing nature . . . , such license shall continue in effect without further action by the Commission until such time as the Commission shall make a final determination with respect to the renewal application”).