

## **Annex C: Internal EUT Photos**



EUT, housing opened, view 1\*




EUT, housing opened, view 2\*

 Examiner:
 Sebasstian KREHS
 Report Number:
 F231771E4 2<sup>nd</sup> version


 Date of issue:
 23.04.2024
 Order Number:
 23-111771
 page 1 of 3



## **Annex C: Internal EUT Photos**



EUT, housing opened, view 3\*




PCB, top view\*

 Examiner:
 Sebasstian KREHS
 Report Number:
 F231771E4 2<sup>nd</sup> version

 Date of issue:
 23.04.2024
 Order Number:
 23-111771
 page 2 of 3



## **Annex C: Internal EUT Photos**



PCB, bottom view\*

Remark\*:The photos are showing an identical EUT with black housing in stead of the tested EUT with white housing.

 Examiner:
 Sebasstian KREHS
 Report Number:
 F231771E4 2<sup>nd</sup> version

 Date of issue:
 23.04.2024
 Order Number:
 23-111771
 page 3 of 3