



Report No.: EED32O81791701 Page 52 of 69

## **8 PHOTOGRAPHS OF TEST SETUP**

Test Model No.: AM05




Radiated spurious emission Test Setup-1(Below 1GHz-Left)




Radiated spurious emission Test Setup-1(Below 1GHz-Right)



Report No.: EED32O81791701 Page 53 of 69



Radiated spurious emission Test Setup-2(Above 1GHz-Left)




Radiated spurious emission Test Setup-2(Above 1GHz-Right)





Report No.: EED32O81791701 Page 54 of 69



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission(Left)

















